



Ethershield 1.2.3 Release Notes

October 17, 2008

What's new in Ethershield 1.2.3

Issues Solved

- Fixed Ethershield activation redirect error for reactivations on 1.2.x.
- Fixed display of some active default gateways.
- Fixed routing interface bug that appeared after reactivations.
- Fixed incorrect link on control start scripts.
- Fixed bug that allowed improperly named Policies.

New Features

- No new features.

Downloading and Installing

To download and install the update, just point your browser to <http://admin.ethershield.com>, and log in. Click on "Software Updates" and "Check for Updates". You should then see a screen showing you your current version details, as well as the details of the new version. All you need to do then, is click on the "Install Version 1.2.3" button. Your Ethershield will download and install the update, and restart automatically. The entire process may take a few minutes depending on your bandwidth. Do not close your browser window while your Ethershield is downloading the new firmware. During the update process, content control and Internet access may be temporarily unavailable.

Known Issues

There are no known issues associated with this release.